



GENERAL SIDEWALK REPAIR LOCATIONS

PROPOSED CONCRETE SIDEWALK REPAIR LOCATIONS SHOWN ON AERIAL IMAGERY ARE FOR GENERAL LOCATION REFERENCE. ACTUAL FLAGS TO BE REMOVED AND REPLACED SHALL BE MARKED BY FIELD ENGINEER DURING CONSTRUCTION.

DRAWN BY:	DATE:
J. ENSLEY	06-24-21
CHECKED BY:	DATE:
J. ENSLEY	06-24-21
PROJECT MANAGER:	BID PLAN DATE:
T. SOVEL	06-24-21

SPALDING DEDECKER Engineers | Surveyors Phone: (248) 844-5400 Fax: (248) 844-5440

905 South Blvd. East Rochester Hills, MI 48307 www.sda-eng.com PHEASANT RUN ROADWAY MAINTENANCE ASSOCIATION (PRRM. **CANTON TOWNSHIP** PHEASANT VIEW SUBDIVISION **GENERAL SIDEWALK REPAIR LOCATIONS**

JOB No.	DRAWING No.
NP21064	NP21064SPL
SCALE:	SHEET
NONE	3 OF 4
	NP21064 SCALE: